

Viglen Desktop BIOS and Drivers Approved List - 05/05/2006

Product	BIOS Version	Windows 2000 Drivers	Windows XP Drivers	Windows XP x64 Drivers	Link To files
Viglen Vig535B	V11	Chipset: 7.2.0.1170 Audio: 5.10.0.5350 VGA: 4.14.10.3530 LAN: 5.505.1004.2002	Chipset: 7.2.0.1170 Audio: 5.10.0.5350 VGA: 4.14.10.3530 LAN: 5.505.1004.2002	Not Supported	ftp://ftp.viglen.co.uk/files/Motherboards/Vig535B/
Viglen Vig550B	V01	Chipset: 7.2.0.1170 Audio: 5.10.0.5780 VGA: 6.14.10.3530 LAN: 2.0.1039.1180 SATA: 5.1.1039.1070	Chipset: 7.2.0.1170 Audio: 5.10.0.5780 VGA: 6.14.10.3530 LAN: 2.0.1039.1180 SATA: 5.1.1039.1070	Not Supported	ftp://ftp.viglen.co.uk/files/Motherboards/Vig550B/
Viglen Vig555M	V0206	Chipset: 7.2.0.1170 Audio: 5.10.0.5780 VGA: 6.14.10.3530 LAN: 2.0.1039.1180 SATA: 5.1.1039.1050	Chipset: 7.2.0.1170 Audio: 5.10.0.5780 VGA: 6.14.10.3530 LAN: 2.0.1039.1180 SATA: 5.1.1039.1050	Not Supported	ftp://ftp.viglen.co.uk/files/Motherboards/Vig555M/
Viglen Vig560S	V1013	Chipset: 7.0.0.1025 Audio: 5.10.0.5125 VGA: 14.14.0.4332 LAN: 10.0 USB 2.0: 5.1.2600.0	Chipset: 7.0.0.1025 Audio: 5.10.0.5125 VGA: 14.14.0.4332 LAN: 10.0	Chipset: 7.0.0.1025 Audio: 5.10.0.5127 VGA: 14.13.64.4323 LAN: 10.0	ftp://ftp.viglen.co.uk/files/Motherboards/Vig560S/
Viglen Vig565S	V1013	Chipset: 7.0.0.1025 Audio: 5.10.0.5125 VGA: 14.14.0.4332 LAN: 10.0 USB 2.0: 5.1.2600.0	Chipset: 7.0.0.1025 Audio: 5.10.0.5125 VGA: 14.14.0.4332 LAN: 10.0	Chipset: 7.0.0.1025 Audio: 5.10.0.5127 VGA: 14.13.64.4323 LAN: 10.0	ftp://ftp.viglen.co.uk/files/Motherboards/VIG565S/
Viglen Vig566S	V0402	Chipset: 7.0.0.1025 Audio: 5.10.0.5125 VGA: 14.14.0.4332 LAN: 10.0 USB 2.0: 5.1.2600.0	Chipset: 7.0.0.1025 Audio: 5.10.0.5125 VGA: 14.14.0.4332 LAN: 10.0	Chipset: 7.0.0.1025 Audio: 5.10.0.5127 VGA: 14.13.64.4323 LAN: 10.0	ftp://ftp.viglen.co.uk/files/Motherboards/Vig566S/
Intel D915GLVG	VG91510A.86A.0048	Chipset: 7.0.0.1025 Audio: 5.10.0.5136 VGA: 14.14.0.4332 LAN: 10.0	Chipset: 7.0.0.1025 Audio: 5.10.0.5136 VGA: 14.14.0.4332 LAN: 10.0	Chipset: 7.0.0.1025 Audio: 5.10.0.5136 VGA: 14.13.64.4323 LAN: 10.0	ftp://ftp.viglen.co.uk/files/Motherboards/D915GLVG/
Intel D915GHA	EV91510A.86A.0478	Chipset: 7.0.0.1025 Audio: 5.10.0.5136 VGA: 14.14.0.4332 LAN: 8.25.2.3 TPM: 1.70.0155.00	Chipset: 7.0.0.1025 Audio: 5.10.0.5136 VGA: 14.14.0.4332 LAN: 8.25.2.3 TPM: 1.70.0155.00	Chipset: 7.0.0.1025 Audio: 5.10.0.5136 VGA: 14.13.64.4323 LAN: 8.27.3.3 TPM: 1.80.0001.00	ftp://ftp.viglen.co.uk/files/Motherboards/D915GHA/
Intel D945PLM	SN94510J.86A.0065	Chipset: 7.0.0.1025 Audio: 5.10.4455.0 LAN: 10.0	Chipset: 7.0.0.1025 Audio: 5.10.4647.0 LAN: 10.0	Chipset: 7.0.0.1025 Audio: 5.10.4647.0 LAN: 10.0	ftp://ftp.viglen.co.uk/files/Motherboards/D945PLM/
Intel D945GTP	NT94510J.86A.3309	Chipset: 7.0.0.1025 Audio: 5.10.4455.0 VGA: 14.14.0.4332 LAN: 10.0	Chipset: 7.0.0.1025 Audio: 5.10.4647.0 VGA: 14.14.0.4332 LAN: 10.1	Chipset: 7.0.0.1025 Audio: 5.10.4647.0 VGA: 14.13.64.4323 LAN: 10.0	ftp://ftp.viglen.co.uk/files/Motherboards/D945GTP/
Intel D925XECV2	CV92510A.86A.0478	Chipset: 7.0.0.1025 Audio: 5.10.0.5136 LAN: 8.25.2.3 App Accelerator: 4.6.0.6758 TPM: 1.70.155.00	Chipset: 7.0.0.1025 Audio: 5.10.0.5136 LAN: 8.25.2.3 App Accelerator: 4.6.0.6758 TPM: 1.70.155.00	Chipset: 7.0.0.1025 Audio: 5.10.0.5136 LAN: 8.27.3.3 TPM: 1.80.0001.00	ftp://ftp.viglen.co.uk/files/Motherboards/D925XCV/
Intel D955XBK	BK95510J.86.A.2024	Chipset: 7.0.0.1025 Audio: 5.10.4455.0 LAN: 10.0 RAID: 5.0.0.1032	Chipset: 7.0.0.1025 Audio: 5.10.4647.0 LAN: 10.0 RAID: 5.0.0.1032	Chipset: 7.0.0.1025 Audio: 5.10.4647.0 LAN: 10.0 RAID: 5.0.0.1032	ftp://ftp.viglen.co.uk/files/Motherboards/D955XBK/
Viglen Vig390S	V1007	Chipset: 6.0.1.1002 Audio: 5.12.1.4010 LAN: 7.73.0.0 USB 2.0: 2.58 RAID: 4.00.041	Chipset: 6.0.1.1002 Audio: 5.12.1.4010 LAN: 7.73.0.0 USB 2.0: 2.58 RAID: 4.00.041	Chipset: 7.0.0.1025 Audio: 5.12.2.5280 LAN: 8.39.1.0 RAID: Not Supported	ftp://ftp.viglen.co.uk/files/Motherboards/Vig390S/
Viglen VM3	V0916	Chipset: 5.00.1012 Audio: 11L VGA: 6.13.01.3485 LAN: 5.602.619.2003	Chipset: 5.00.1012 Audio: 11L VGA: 6.13.01.3485 LAN: 5.602.619.2003	Not Supported	ftp://ftp.viglen.co.uk/files/Viglen_VM3/Viglen_VM3/
Viglen VM3-B	V0504	Chipset: 6.2.1.1001 Audio: A367 VGA: 6.14.10.3943 LAN: 616	Chipset: 6.2.1.1001 Audio: A367 VGA: 6.14.10.3943 LAN: 616	Not Supported	ftp://ftp.viglen.co.uk/files/Viglen_VM3/Viglen_VM3-B/
Viglen VM4	No Update	Chipset: 7.0.0.1025 Audio: 5.10.0.5620 VGA: 14.14.0.4332 LAN: 7.73.0 Wireless LAN: 2.23.1129.2004	Chipset: 7.0.0.1025 Audio: 5.10.0.5620 VGA: 14.14.0.4332 LAN: 7.73.0 Wireless LAN: 2.23.1129.2004	Not Supported	ftp://ftp.viglen.co.uk/files/Viglen_VM_Series/Viglen_VM4/
Viglen Omnino (L29xP)	V0303	Chipset: 5.00.1012 Audio: 5.10.0.5170 VGA: 6.14.10.3762 LAN: 5.505.1004 Modem: 3.20.04 PCMCIA: 5.0.2195	Chipset: 5.00.1012 Audio: 5.10.0.5170 VGA: 6.14.10.3762 LAN: 5.505.1004 Modem: 3.20.04 PCMCIA: 5.0.2195	Not Supported	ftp://ftp.viglen.co.uk/files/Omnino_Series/Omnino/L29xP/
Viglen Omnino+ (L29xU)	V0310	Chipset: 5.00.1012 Audio: 5.10.0.5170 VGA: 6.14.10.3762 LAN: 5.505.1004 Modem: 3.20.04 PCMCIA: 5.0.2195	Chipset: 5.00.1012 Audio: 5.10.0.5170 VGA: 6.14.10.3762 LAN: 5.505.1004 Modem: 3.20.04 PCMCIA: 5.0.2195	Not Supported	ftp://ftp.viglen.co.uk/files/Omnino_Series/Omnino/L29xU/
Viglen Omnino-T (L29xT)	V0107	Chipset: 6.3.0.1007 Audio: 5.10.0.5780 VGA: 6.14.10.3943 LAN: 5.620.1202.2004 Modem: 4.0.6.1116 PCMCIA: 5.0.2195	Chipset: 6.3.0.1007 Audio: 5.10.0.5780 VGA: 6.14.10.3943 LAN: 5.620.1202.2004 Modem: 4.0.6.1116 PCMCIA: 5.0.2195	Not Supported	ftp://ftp.viglen.co.uk/files/Omnino_Series/Omnino/L29xT/