

Viglen Server BIOS, Firmware and Drivers Approved List - 05/05/2006

Product	BIOS Version	Firmware Version	Management Software	Windows 2000 Drivers	Windows 2003 Drivers	Link To files
BX120 Server	V1.1b	N/A	Super Doctor III - V1.5.029	Chipset: 5.1.1.1002 LAN: 7.2.17.0 SATA: 3.5.0.2568 VGA: 6.14.10.4020 AUDIO: 5.10.0.5790	Chipset: 5.1.1.1002 LAN: 7.2.17.0 SATA: 3.5.0.2568 AUDIO: 5.10.0.5790	ftp://ftp.viglen.co.uk/files/Servers/BX120/
BX130 Server	V1.0b	N/A	Super Doctor III - V1.5.029	Chipset: 7.2.0.1006 LAN: 10.1 SATA: 5.0.0.1032 VGA: 6.14.10.4308 AUDIO: 5.10.0.5830	Chipset: 7.2.0.1006 LAN: 10.1 SATA: 5.0.0.1032 VGA: 6.14.10.4308 AUDIO: 5.10.0.5830	ftp://ftp.viglen.co.uk/files/Servers/BX130/
CX130 Server	V1.0c	N/A	Super Doctor III - V1.5.029	Chipset: 6.2.0.1005 LAN: 7.2.17.0 SATA: 2.01.021 LSI SCSI: 6.2.0	Chipset: 6.2.0.1005 LAN: 7.2.17.0 SATA: 2.01.021 LSI SCSI: 6.2.0	ftp://ftp.viglen.co.uk/files/Servers/CX130_SX140_SX240-L/
CX135 Server	V1.0c	N/A	Super Doctor III - V1.5.029	Chipset: 7.2.0.1006 LAN: 8.5.14.0 SATA: 2.01.021 LSI SCSI: 6.2.0	Chipset: 7.2.0.1006 LAN: 8.5.14.0 SATA: 2.01.021 LSI SCSI: 6.2.0	ftp://ftp.viglen.co.uk/files/Servers/CX135_SX145_SX245-L/
LX270 Server	RC01.0060	BMC: 0.48 FRUSDR: 6.6.6	ISM 8.40	Chipset: 6.2.1.1001 Intel LAN: 7.4.19.0 Marvell LAN: 7.19.1.3 LSI SCSI: 1.09.11	Chipset: 6.2.1.1001 Intel LAN: 7.4.19.0 Marvell LAN: 7.19.1.3 LSI SCSI: 1.09.11	ftp://ftp.viglen.co.uk/files/Servers/LX270/
LX275 Server	P02.014	BMC: 0.48 FRUSDR: 6.6.6	ISM 8.40	Chipset: 7.2.1.1003 Intel LAN: 8.6.11.0 Marvell LAN: 7.19.1.3 LSI SCSI: 1.09.11	Chipset: 7.2.1.1003 Intel LAN: 8.6.11.0 Marvell LAN: 8.25.1.3 LSI SCSI: 1.10.02	ftp://ftp.viglen.co.uk/files/Servers/LX275/
XX230 Server	P08.101	BMC: 0.48 FRUSDR: 6.6.3 HSC SATA: 1.08 HSC SCSI-4: 1.12 HSC SCSI-6: 1.12	ISM 8.40	Chipset: 6.0.1.1002 LAN: 8.4.21.0 LSI SCSI: 1.09.11 SATA RAID: 4.2.1118.2004	Chipset: 6.0.1.1002 LAN: 8.4.21.0 LSI SCSI: 1.09.11 SATA RAID: 4.2.1118.2004	ftp://ftp.viglen.co.uk/files/Servers/XX230/
XX415 Server	P15	BMC: 0.28 FRUSDR: 5.6.A HSC: 0.8	ISM 5.5.6	Hot Plug PCI: 5.1.1.1 Adaptec SCSI: V2.0 LAN: 7.0.36	Hot Plug PCI: 5.1.1.1 Adaptec SCSI: V2.0 LAN: 7.0.36	ftp://ftp.viglen.co.uk/files/Servers/XX415/
XX420 Server	P04.008	BMC: 0.34 FRUSDR: 6.0.24 HSC: 1.6	ISM 8.40	Chipset: 7.2.1.1003 VGA: 6.14.10.6497 LAN: 7100c	Chipset: 7.2.1.1003 VGA: 6.14.10.6497 LAN: 7100c	ftp://ftp.viglen.co.uk/files/Servers/XX420/
SX140 Server	V1.0c	N/A	Super Doctor III - V1.5.029	Chipset: 6.2.0.1005 LAN: 7.2.17.0 SATA: 2.01.021 LSI SCSI: 6.2.0	Chipset: 6.2.0.1005 LAN: 7.2.17.0 SATA: 2.01.021 LSI SCSI: 6.2.0	ftp://ftp.viglen.co.uk/files/Servers/CX130_SX140_SX240-L/
SX145 Server	V1.0c	N/A	Super Doctor III - V1.5.029	Chipset: 7.2.0.1006 LAN: 8.5.14.0 SATA: 2.01.021 LSI SCSI: 6.2.0	Chipset: 7.2.0.1006 LAN: 8.5.14.0 SATA: 2.01.021 LSI SCSI: 6.2.0	ftp://ftp.viglen.co.uk/files/Servers/CX135_SX145_SX245-L/
SX240 Server	P08.081	BMC: 0.47 FRUSDR: 6.6.3 HSC SATA: 1.08 HSC SCSI: 1.06	ISM 8.40	Chipset: 6.0.1.1002 LAN: 8.4.21.0 SATA RAID: 4.2.1118.2004 LSI SCSI: 1.09.11	Chipset: 6.0.1.1002 LAN: 8.4.21.0 SATA RAID: 4.2.1118.2004 LSI SCSI: 1.09.11	ftp://ftp.viglen.co.uk/files/Servers/SX240/
SX240-L Server	V1.0c	N/A	Super Doctor III - V1.5.029	Chipset: 6.2.0.1005 LAN: 7.2.17.0 SATA: 2.01.021 LSI SCSI: 6.2.0	Chipset: 6.2.0.1005 LAN: 7.2.17.0 SATA: 2.01.021 LSI SCSI: 6.2.0	ftp://ftp.viglen.co.uk/files/Servers/CX130_SX140_SX240-L/
SX245-L Server	V1.0c	N/A	Super Doctor III - V1.5.029	Chipset: 7.2.0.1006 LAN: 8.5.14.0 SATA: 2.01.021 LSI SCSI: 6.2.0	Chipset: 7.2.0.1006 LAN: 8.5.14.0 SATA: 2.01.021 LSI SCSI: 6.2.0	ftp://ftp.viglen.co.uk/files/Servers/CX135_SX145_SX245-L/