

Viglen Server BIOS, Firmware and Drivers Approved List - 05/05/2006

| Product | BIOS Version | Firmware Version | Management Software | Windows 2000 Drivers | Windows 2003 Drivers | Link To files |
|----------------|--------------|--|-----------------------------|---|---|---|
| BX120 Server | V1.1b | N/A | Super Doctor III - V1.5.029 | Chipset: 5.1.1.1002 LAN: 7.2.17.0 SATA: 3.5.0.2568 VGA: 6.14.10.4020 AUDIO: 5.10.0.5790 | Chipset: 5.1.1.1002 LAN: 7.2.17.0 SATA: 3.5.0.2568 AUDIO: 5.10.0.5790 | ftp://ftp.viglen.co.uk/files/Servers/BX120/ |
| BX130 Server | V1.0b | N/A | Super Doctor III - V1.5.029 | Chipset: 7.2.0.1006 LAN: 10.1 SATA: 5.0.0.1032 VGA: 6.14.10.4308 AUDIO: 5.10.0.5830 | Chipset: 7.2.0.1006 LAN: 10.1 SATA: 5.0.0.1032 VGA: 6.14.10.4308 AUDIO: 5.10.0.5830 | ftp://ftp.viglen.co.uk/files/Servers/BX130/ |
| CX130 Server | V1.0c | N/A | Super Doctor III - V1.5.029 | Chipset: 6.2.0.1005 LAN: 7.2.17.0 SATA: 2.01.021 LSI SCSI: 6.2.0 | Chipset: 6.2.0.1005 LAN: 7.2.17.0 SATA: 2.01.021 LSI SCSI: 6.2.0 | ftp://ftp.viglen.co.uk/files/Servers/CX130_SX140_SX240-L/ |
| CX135 Server | V1.0c | N/A | Super Doctor III - V1.5.029 | Chipset: 7.2.0.1006 LAN: 8.5.14.0 SATA: 2.01.021 LSI SCSI: 6.2.0 | Chipset: 7.2.0.1006 LAN: 8.5.14.0 SATA: 2.01.021 LSI SCSI: 6.2.0 | ftp://ftp.viglen.co.uk/files/Servers/CX135_SX145_SX245-L/ |
| LX270 Server | RC01.0060 | BMC: 0.48 FRUSDR: 6.6.6 | ISM 8.40 | Chipset: 6.2.1.1001 Intel LAN: 7.4.19.0 Marvell LAN: 7.19.1.3 LSI SCSI: 1.09.11 | Chipset: 6.2.1.1001 Intel LAN: 7.4.19.0 Marvell LAN: 7.19.1.3 LSI SCSI: 1.09.11 | ftp://ftp.viglen.co.uk/files/Servers/LX270/ |
| LX275 Server | P02.014 | BMC: 0.48 FRUSDR: 6.6.6 | ISM 8.40 | Chipset: 7.2.1.1003 Intel LAN: 8.6.11.0 Marvell LAN: 7.19.1.3 LSI SCSI: 1.09.11 | Chipset: 7.2.1.1003 Intel LAN: 8.6.11.0 Marvell LAN: 8.25.1.3 LSI SCSI: 1.10.02 | ftp://ftp.viglen.co.uk/files/Servers/LX275/ |
| XX230 Server | P08.101 | BMC: 0.48 FRUSDR: 6.6.3 HSC SATA: 1.08 HSC SCSI-4: 1.12 HSC SCSI-6: 1.12 | ISM 8.40 | Chipset: 6.0.1.1002 LAN: 8.4.21.0 LSI SCSI: 1.09.11 SATA RAID: 4.2.1118.2004 | Chipset: 6.0.1.1002 LAN: 8.4.21.0 LSI SCSI: 1.09.11 SATA RAID: 4.2.1118.2004 | ftp://ftp.viglen.co.uk/files/Servers/XX230/ |
| XX415 Server | P15 | BMC: 0.28 FRUSDR: 5.6.A HSC: 0.8 | ISM 5.5.6 | Hot Plug PCI: 5.1.1.1 Adaptec SCSI: V2.0 LAN: 7.0.36 | Hot Plug PCI: 5.1.1.1 Adaptec SCSI: V2.0 LAN: 7.0.36 | ftp://ftp.viglen.co.uk/files/Servers/XX415/ |
| XX420 Server | P04.008 | BMC: 0.34 FRUSDR: 6.0.24 HSC: 1.6 | ISM 8.40 | Chipset: 7.2.1.1003 VGA: 6.14.10.6497 LAN: 7100c | Chipset: 7.2.1.1003 VGA: 6.14.10.6497 LAN: 7100c | ftp://ftp.viglen.co.uk/files/Servers/XX420/ |
| SX140 Server | V1.0c | N/A | Super Doctor III - V1.5.029 | Chipset: 6.2.0.1005 LAN: 7.2.17.0 SATA: 2.01.021 LSI SCSI: 6.2.0 | Chipset: 6.2.0.1005 LAN: 7.2.17.0 SATA: 2.01.021 LSI SCSI: 6.2.0 | ftp://ftp.viglen.co.uk/files/Servers/CX130_SX140_SX240-L/ |
| SX145 Server | V1.0c | N/A | Super Doctor III - V1.5.029 | Chipset: 7.2.0.1006 LAN: 8.5.14.0 SATA: 2.01.021 LSI SCSI: 6.2.0 | Chipset: 7.2.0.1006 LAN: 8.5.14.0 SATA: 2.01.021 LSI SCSI: 6.2.0 | ftp://ftp.viglen.co.uk/files/Servers/CX135_SX145_SX245-L/ |
| SX240 Server | P08.081 | BMC: 0.47 FRUSDR: 6.6.3 HSC SATA: 1.08 HSC SCSI: 1.06 | ISM 8.40 | Chipset: 6.0.1.1002 LAN: 8.4.21.0 SATA RAID: 4.2.1118.2004 LSI SCSI: 1.09.11 | Chipset: 6.0.1.1002 LAN: 8.4.21.0 SATA RAID: 4.2.1118.2004 LSI SCSI: 1.09.11 | ftp://ftp.viglen.co.uk/files/Servers/SX240/ |
| SX240-L Server | V1.0c | N/A | Super Doctor III - V1.5.029 | Chipset: 6.2.0.1005 LAN: 7.2.17.0 SATA: 2.01.021 LSI SCSI: 6.2.0 | Chipset: 6.2.0.1005 LAN: 7.2.17.0 SATA: 2.01.021 LSI SCSI: 6.2.0 | ftp://ftp.viglen.co.uk/files/Servers/CX130_SX140_SX240-L/ |
| SX245-L Server | V1.0c | N/A | Super Doctor III - V1.5.029 | Chipset: 7.2.0.1006 LAN: 8.5.14.0 SATA: 2.01.021 LSI SCSI: 6.2.0 | Chipset: 7.2.0.1006 LAN: 8.5.14.0 SATA: 2.01.021 LSI SCSI: 6.2.0 | ftp://ftp.viglen.co.uk/files/Servers/CX135_SX145_SX245-L/ |